

Energy Converters – Computer-Aided Design (CAD) and System Dynamics



A. Binder

Institut für Elektrische Energiewandlung
Technische Universität Darmstadt



Introduction

Lecturer



TECHNISCHE
UNIVERSITÄT
DARMSTADT

Lecturer

Prof. Dr.-Ing. habil. Dr. h.c. Andreas Binder
Institut für Elektrische Energiewandlung
TU Darmstadt
64283, Landgraf-Georg-Straße 4, Darmstadt
tel.: +49-6151-16-24181 o. 24180
fax.:+49-6151-16-24183
e-mail: abinder@ew.tu-darmstadt.de

Tutorial

M. Sc. Alexander Möller
Institut für Elektrische Energiewandlung
TU Darmstadt
64283, Landgraf-Georg-Straße 4, Darmstadt
tel.: +49-6151-16-24188
fax.:+49-6151-16-24183
e-mail: amoeller@ew.tu-darmstadt.de



Introduction

Learning outcomes



Understanding of **design rules for electrical machines**

- scaling laws (typical for power engineering)
i.e. AC and DC motors and generators

Knowledge of **design of AC machinery, here: cage induction machine**

- Magnetic circuit and winding topology
- Calculation of resistances and inductances
- Losses and efficiency

Knowledge of **basics in cooling systems and temperature calculation**

- applications in electrical motors and generators

Understanding of **dynamics of DC and AC machinery**

- system dynamics of variable speed drives & space vector theory
- transients in generator systems & power stability

Calculation examples for self-training

Introduction

Contents



TECHNISCHE
UNIVERSITÄT
DARMSTADT

1. Basic design rules for electrical machines
2. Design of Induction Machines
3. Heat transfer and cooling of electrical machines
4. Dynamics of electrical machines
5. Dynamics of DC machines
6. Space vector theory
7. Dynamics of induction machines
8. Dynamics of synchronous machines



Source:
SPEED program


Introduction

Organization



TECHNISCHE
UNIVERSITÄT
DARMSTADT

- Moodle:
[Down-load of slides, text book & Collection of exercises](#)
- [CityCopies](#), Holzstraße 5:
Paper copies of
[slides, text book & Collection of exercises](#)
- [Introduction](#) of two computer programs:
 - [SPEED program](#): Induction machine design
 - [Matlab/SIMULINK](#) for dynamic calculations
- [Excursion](#) offered



Source:
SPEED program



Introduction

Examination



TECHNISCHE
UNIVERSITÄT
DARMSTADT

- **Examination:** In written form

Details see - Moodle


or

- Institute EW Homepage

- a) Three calculation examples
- b) Theoretical questions

- **Homework:**

Dynamics examples – add-on points, if positive examination result



Source:
SPEED program

Introduction

Examination



TECHNISCHE
UNIVERSITÄT
DARMSTADT

Written examination

Winter term: 2 partial exams

Summer term: 1 exam

**Calculation examples & List of theory questions:
see “Collection of Exercises”**

Introduction Symbols



- **Used symbols:** see „Text book“

- **Greek alphabet:**

$A \alpha$	Alpha	$B \beta$	Beta	$\Gamma \gamma$	Gamma	$\Delta \delta$	Delta
$E \varepsilon$	Epsilon	$Z \zeta$	Zeta	$H \eta$	Eta	$\Theta \vartheta$	Theta
$I \iota$	Jota	$K \kappa$	Kappa	$\Lambda \lambda$	Lambda	$M \mu$	My (mue)
$N \nu$	Ny (nue)	$\Xi \xi$	Xi	$O \circ$	Omicron	$\Pi \pi$	Pi
$P \rho$	Rho	$\Sigma \sigma$	Sigma	$T \tau$	Tau	$Y \upsilon$	Ypsilon
$\Phi \varphi$	Phi	$X \chi$	Chi	$\Psi \psi$	Psi	$\Omega \omega$	Omega



1. Basic design rules for electrical machines

2. Design of Induction Machines

3. Heat transfer and cooling of electrical machines

4. Dynamics of electrical machines

5. Dynamics of DC machines

6. Space vector theory

7. Dynamics of induction machines


8. Dynamics of synchronous machines



Source:
SPEED program



Basic design rules for electrical machines



Source: Winergy, Germany



1. Basic design rules for rotating machines

1.1 Torque generation and internal power


1.2 Electromagnetic utilization

1.3 Thermal utilization

1.4 Overload capability of AC machines


1. Basic design rules for electrical machines

Cross section of a cage induction machine



1. Basic design rules for electrical machines

Air gap field, excited by slot conductors



Assumption: $\mu_{Fe} \rightarrow \infty : H_{Fe} = 0$

$$\text{Ampere's law: } \Theta_Q = \oint_C \vec{H} \cdot d\vec{s} = \int_{C_{Fe}} \vec{H}_{Fe} \cdot d\vec{s} + \int_{C_\delta} \vec{H}_\delta \cdot d\vec{s} = \int_{C_\delta} \vec{H}_\delta \cdot d\vec{s}$$


Case 1: Tangential air gap field along path 1: $\Theta_Q = \int_{C_{\delta_1}} \vec{H}_\delta \cdot d\vec{s} = H_{\delta_1} \cdot s_Q \Rightarrow H_{\delta_1} = \Theta_Q / s_Q$

Case 2: Radial air gap field along path 2: $\Theta_Q = \int_{C_{\delta_2}} \vec{H}_\delta \cdot d\vec{s} = H_{\delta_2} \cdot 2\delta \Rightarrow H_{\delta_2} = \Theta_Q / (2\delta)$

The same air gap field is obtained at $\mu_{Fe} \rightarrow \infty$

- a) for the real slot geometry and
- b) for the current loading model.

Current loading A introduced to replace the slot geometry



Source:


H. Kleinrath, Studientext
1975, Wiesbaden

1. Basic design rules for electrical machines

Resulting air gap field at the slot



Rotor



- Only stator self field of slot conductor


$$B_{\delta s} = \frac{\mu_0 \Theta_Q}{2\delta}$$

- No external rotor field

$$B_{\delta r} = 0$$

Source: H. Kleinrath, Studentext 1975,
Wiesbaden

Resulting air gap field




- No stator self field of slot conductor

$$B_{\delta s} = 0$$

- Only external rotor field

$$B_{\delta r} > 0$$



Superposition of:

- Stator self field of slot conductor

$$B_{\delta s} = \frac{\mu_0 \Theta_Q}{2\delta}$$


and external rotor field

$$B_{\delta r} > 0$$

Note: For simple superposition we have to assume $\mu_{Fe}(x,y) = \text{const.}$

1. Basic design rules for electrical machines

Magnetic force F_e on a slot conductor



External rotor field is at the slot conductor location very small:

$$B_{c,r} \ll B_{\delta r}$$

Source:

H. Kleinrath, Studentext
1975, Wiesbaden

LORENTZ-force F_c on the slot conductor is very small:

$$F_c = l \cdot \Theta_Q \cdot B_{c,r}$$

Magnetic pull force F_M due to *MAXWELL* stress f_n on magnetized iron dominates!

$$F_M = \int_{A_{Fe}} f_n \cdot dA_{Fe} \quad f_n \approx B_n^2 / (2\mu_0)$$

$$F_M = \frac{l}{2\mu_0} \cdot \int_y (B_{right}^2 - B_{left}^2) \cdot dy$$

Resulting magnetic force F_e :

$$F_e = F_c + F_M$$

ca. 10 % ca. 90 %

$$F_e = l \cdot \Theta_Q \cdot B_{\delta,r}$$



Mathematical proof:
Williams-Mamak: IEE Trans. C,
1961, Monograph no. 456U

$$F_M = F_{M,right} - F_{M,left}$$



1. Basic design rules for electrical machines

Simplified model for conductor force F_e



Source:

H. Kleinrath, Studientext
1975, Wiesbaden

LORENTZ-force F_e on a SURFACE conductor yields the same force as the exact model of a slot conductor:


$$F_e = l \cdot \Theta_Q \cdot B_{\delta,r}$$

$$F_e = F_c + F_M$$

$$F_e = l \cdot \Theta_Q \cdot B_{\delta,r}$$

The same force is obtained

- a) for the real slot geometry and
- b) for the surface conductor model, leading again to a current loading model $A(x_s)$.



Slotting replaced by “discrete” current loading


e.g.: $m = 3$, $q = 2$, $W/\tau_p = 1$

1. Basic design rules for electrical machines

m.m.f. $V(x_s)$ & current loading $A(x_s)$ in AC machines



Distributed three-phase winding excites a distributed stator field:



Fundamental of m.m.f. distribution $V(x_s)$ is a sine wave:

$$\hat{V}_1 \cdot \sin(x_s \pi / \tau_p - \omega t) \quad V(x_s) = H_\delta(x_s) \cdot \delta$$

Current loading is derivative of m.m.f.: $V(x_s) = \int A(x_s) \cdot dx_s$

$$A_1(x_s, t) = \frac{d}{dx_s} (\hat{V}_1 \cdot \sin(x_s \pi / \tau_p - \omega t))$$

$$A_1(x_s, t) = \frac{\hat{V}_1 \pi}{\tau_p} \cdot \cos(x_s \pi / \tau_p - \omega t)$$

$$\hat{A}_1 = \hat{V}_1 \cdot \pi / \tau_p = \left(\frac{\sqrt{2}}{\pi} \cdot \frac{m}{p} \cdot N \cdot k_{w1} \cdot I \right) \cdot \pi / \tau_p$$


Fundamental current loading $A_1(x_s)$ is a continuous function, not any longer “discrete” like single conductors!

1. Basic design rules for electrical machines

Fundamental m.m.f. $V_1(x_s)$, air-gap field $B_{\delta 1}(x_s)$
& current loading $A_1(x_s)$



TECHNISCHE
UNIVERSITÄT
DARMSTADT



Stator winding:

Fundamental m.m.f. distribution $V(x_s)$ as sine wave:

$$V_1(x_s, t) = \hat{V}_1 \cdot \sin(x_s \pi / \tau_p - \omega t)$$

Stator fundamental air-gap field distribution $B_\delta(x_s)$ as sine wave at $\mu_{Fe} \rightarrow \infty$:

$$B_\delta(x_s, t) = \mu_0 \cdot V(x_s, t) / \delta = \hat{B}_{\delta 1} \sin(x_s \pi / \tau_p - \omega t)$$


Current loading is derivative of m.m.f.:

$$A_1(x_s, t) = dV_1(x_s, t) / dt = \hat{A}_1 \cdot \cos(x_s \pi / \tau_p - \omega t)$$

Fundamental current loading $A_1(x_s)$ is a continuous function, not any longer “discrete” like single conductors!

1. Basic design rules for electrical machines

LORENTZ force



z: total number of conductors

**Total tangential force:
(acting on stator)**

Stator field and rotor current

OR

rotor field and stator current: e.g.:

$$dF(x_s, t) = dz \cdot i_s(x_s, t) \cdot B_{\delta, r}(x_s, t) \cdot l_e$$

Number of conductors per element dx_s :

$$dz = z \cdot \frac{dx_s}{2p\tau_p}$$

With current loading A_s :

$$A_s(x_s, t) = \frac{z_s \cdot i_s(x_s, t)}{2p\tau_p}$$

$$F(t) = l_e \cdot \int_0^{2p\tau_p} A_s(x_s, t) \cdot B_{\delta, r}(x_s, t) \cdot dx_s$$

1. Basic design rules for electrical machines

Self-field does not produce resulting tangential force



TECHNISCHE
UNIVERSITÄT
DARMSTADT

$$F(t) = l_e \cdot \int_{-\frac{2p\tau_p}{2}}^{\frac{2p\tau_p}{2}} A_s(x_s, t) \cdot B_{\delta,s}(x_s, t) \cdot dx_s = 0$$

$$F(t) = l_e \cdot \int_0^{\frac{2p\tau_p}{2}} A_s(x, t) \cdot B_{\delta,r}(x, t) \cdot dx = l_e \cdot \int_0^{\frac{2p\tau_p}{2}} A_s(x_s, t) \cdot (B_{\delta,s}(x_s, t) + B_{\delta,r}(x_s, t)) \cdot dx_s$$

Tangential force on stator:

$$F(t) = l_e \cdot \int_0^{\frac{2p\tau_p}{2}} A_s(x_s, t) \cdot B_{\delta}(x_s, t) \cdot dx_s$$

Tangential force on rotor: “Actio est reactio” (Newton’s 3rd law):


$$F(t) = -l_e \cdot \int_0^{\frac{2p\tau_p}{2}} A_s(x_s, t) \cdot B_{\delta}(x_s, t) \cdot dx_s$$

1. Basic design rules for electrical machines

Fundamental sine wave magnetic air gap travelling field in AC machines



TECHNISCHE
UNIVERSITÄT
DARMSTADT



Magnetic flux per pole:

$$\Phi_h = \frac{2}{\pi} \cdot \tau_p l_e \cdot \hat{B}_{\delta 1}$$

Resulting air gap field fundamental:

$$B_\delta(x_s, t) = \hat{B}_{\delta 1} \cdot \cos(x_s \pi / \tau_p - \omega t)$$

1. Basic design rules for electrical machines

Torque generation in AC machines by fundamental fields (1)



TECHNISCHE
UNIVERSITÄT
DARMSTADT

$$F(t) = l_e \cdot \int_0^{2p\tau_p} A_s(x_s, t) \cdot B_\delta(x_s, t) \cdot dx_s \quad M_e(t) = F(t) \cdot d_{si} / 2 \quad r_{si} = \frac{d_{si}}{2}$$

Generally the tangential force depends on time due to slotting and phase bands +U, -W, +V, -U, +W, -V. Therefore we have a torque ripple $\Delta M_e(t)$:

$$M_e(t) = M_{e,av} + \Delta M_e(t)$$

Considering only fundamental fields we get a CONSTANT torque:

$$M_e(t) = M_{e,av} \quad \Delta M_e(t) = 0$$

$$\rightarrow F_1 = l_e \cdot \int_0^{2p\tau_p} A_{s,1}(x_s, t) \cdot B_{\delta,1}(x_s, t) \cdot dx_s \quad M_{e,AC} = F_1 \cdot d_{si} / 2$$

1. Basic design rules for electrical machines

Torque generation in AC machines by fundamental fields (2)



- **Torque on stator:** $M_{e,AC} = \frac{d_{si}}{2} \cdot l_e \cdot \int_0^{2p\tau_p} A_{s,1}(x_s, t) \cdot B_{\delta,1}(x_s, t) \cdot dx_s$ $\gamma_s = x_s \cdot \pi / \tau_p$
 $d_{si}\pi = 2p\tau_p$

$$M_{e,AC} = \int_0^{2\pi p} \hat{A}_{s1} \cos(\gamma_s - \omega t - \varphi_\delta) \cdot \hat{B}_{\delta,1} \cos(\gamma_s - \omega t) \cdot l_e \cdot p \cdot \left(\frac{\tau_p}{\pi} \right)^2 \cdot d\gamma_s \quad \left. \right\} \gamma_s - \omega t = \xi$$

$$M_{e,AC} = \int_{-\omega t}^{-\omega t + 2\pi p} \hat{A}_{s1} \cos(\xi - \varphi_\delta) \cdot \hat{B}_{\delta,1} \cos \xi \cdot l_e \cdot p \cdot \left(\frac{\tau_p}{\pi} \right)^2 \cdot d\xi$$

$$M_{e,AC} = \hat{A}_{s1} \hat{B}_{\delta,1} \cdot l_e \cdot p \cdot \left(\frac{\tau_p}{\pi} \right)^2 \cdot \int_{-\omega t}^{-\omega t + 2\pi p} [\cos \xi \cdot \cos \varphi_\delta + \sin \xi \cdot \sin \varphi_\delta] \cdot \cos \xi \cdot d\xi \quad \left. \right\} \begin{aligned} \cos^2 \xi &= (1 + \cos(2\xi)) / 2 \\ \cos \xi \sin \xi &= \sin(2\xi) / 2 \end{aligned}$$

$$M_{e,AC} = l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \cos \varphi_\delta / \pi$$

- **Torque on rotor:** “Actio est reactio” (Newton’s 3rd law):

$$M_{e,AC} = -l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \cos \varphi_\delta / \pi$$


1. Basic design rules for electrical machines

Torque generation in AC machines by fundamental fields (3)



Example:

Phase shift between stator current loading and air-gap field: $\varphi_\delta = 315^\circ$



$$M_{e,AC} = l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \cos 315^\circ / \pi$$

$$M_{e,AC} = l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \frac{1}{\sqrt{2}} \cdot \frac{1}{\pi}$$

Positive torque on the stator = in counter-clockwise direction

$$\bar{\varphi}_\delta = \varphi_\delta - 2\pi$$

Note: Due to $\hat{A}_{s1} \cos(\gamma - \omega t - \varphi_\delta) = \hat{A}_{s1} \cos(\gamma_s - \omega t - (\underbrace{\varphi_\delta - 2\pi}_{})) = \hat{A}_{s1} \cos(\gamma_s - \omega t - \bar{\varphi}_\delta)$

we also get: $\bar{\varphi}_\delta = -45^\circ$ $M_{e,AC} = l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \cos(-45^\circ) / \pi$

$$M_{e,AC} = l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \frac{1}{\sqrt{2}} \cdot \frac{1}{\pi}$$


1. Basic design rules for electrical machines

Example: Torque generation in an induction machine




Example:

2 poles, motor operation



Main flux $\Phi_h \sim B_{\delta,1} \sim I_m$ and internal voltage $U_h \sim j \Phi_h$:



Internal phase angle between internal voltage and stator current: $\varphi_i = \varphi_\delta - \pi$


Torque on rotor: $M_{e,AC} = -l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \cos \varphi_\delta / \pi = l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \cos \varphi_i / \pi$
 $(-\cos \varphi_\delta = \cos \varphi_i)$

1. Basic design rules for electrical machines

Internal phase shift φ_i in an induction machine



Example: $0 < \varphi_i < \pi/2$: $M_{e,AC} > 0$ on rotor = motor operation



Phase shift φ_i between I_s and U_h !

Internal power:


$$P_\delta = 2\pi n_{syn} M_{e,AC} = 2\pi \frac{f_s}{p} \cdot l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta 1} \cdot \cos \varphi_i / \pi$$

$$U_h = 2\pi f_s \cdot k_{ws1} N_s \Phi_h / \sqrt{2} \quad \Phi_h = \frac{2}{\pi} \cdot \tau_p l_e \cdot \hat{B}_{\delta 1}$$

$$\hat{A}_{s1} = \frac{\sqrt{2}}{\tau_p} \cdot \frac{m_s}{p} \cdot N_s \cdot k_{ws1} \cdot I_s$$


$$P_\delta = m_s U_h I_s \cdot \cos \varphi_i$$

Phase shift φ_s between I_s and U_s !



1. Basic design rules for electrical machines

Synchronous machine: Internal phase shift φ_i




1. Basic design rules for electrical machines

Phasor diagram of a synchronous machine



Example: $-\pi/2 > \varphi_i > -\pi$: $M_{e,AC} < 0$ on rotor = generator operation



Internal power:

$$P_\delta = 2\pi n_{syn} M_{e,AC} = 2\pi \frac{f_s}{p} \cdot l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta1} \cdot \cos \varphi_i / \pi$$


$$U_h = 2\pi f_s \cdot k_{ws1} N_s \Phi_h / \sqrt{2}$$

$$\Phi_h = \frac{2}{\pi} \cdot \tau_p l_e \cdot \hat{B}_{\delta1}$$

$$P_\delta = m_s U_h I_s \cdot \cos \varphi_i$$


Phase shift φ_i between I_s and U_h

Phase shift φ_s between I_s and U_s



1. Basic design rules for electrical machines

Torque generation in DC machines



$$\Phi = l_e \int_0^{\tau_p} B_{\delta,s}(x_s) \cdot dx_s = \alpha_e \cdot l_e \cdot \tau_p \cdot \hat{B}_{\delta,s} \quad A_r(x_s) = A_r = \frac{z \cdot I_c}{d_{si} \cdot \pi} = \text{const.}$$

Tangential force on rotor:

$$F = l_e \cdot \int_0^{2p\tau_p} A_r(x_s, t) \cdot B_{\delta,s}(x_s, t) \cdot dx_s \quad M_e = F \cdot d_{si} / 2$$

$$M_e = 2p \cdot \frac{d_{si}}{2} \cdot l_e \cdot A_r \cdot \int_0^{\tau_p} B_{\delta,s}(x_s) \cdot dx_s = p \cdot d_{si} \cdot A_r \cdot \Phi \quad M_{e,DC} = l_e \cdot 2(p\tau_p)^2 \cdot A_r \cdot \alpha_e \hat{B}_{\delta,s} / \pi$$

1. Basic design rules for electrical machines


Internal power P_δ in DC machines



$$P_\delta = 2\pi n \cdot M_{e,DC} = 2\pi n \cdot l_e \cdot 2(p\tau_p)^2 \cdot A_r \cdot \alpha_e \hat{B}_{\delta,s} / \pi \quad d_{si} \cdot \pi = 2p \cdot \tau_p$$


$$U_i = \frac{z \cdot p}{a} \cdot n \cdot \Phi \quad \Phi = \alpha_e \cdot l_e \cdot \tau_p \cdot \hat{B}_{\delta,s} \quad A_r = \frac{z \cdot I_c}{d_{si} \cdot \pi} \quad I_a = 2a \cdot I_c$$

$$P_\delta = U_i \cdot I_a$$



1. Basic design rules for electrical machines

Summary: Torque generation



$$F = l_e \cdot \int_0^{2p\tau_p} A(x_s, t) \cdot B_\delta(x_s, t) \cdot dx_s$$

$$M_e = F \cdot d_{si} / 2$$

AC machines: Current loading A_s and air gap flux density B_δ are sinusoidal distributed, phase shift φ_i between I_s and U_h :

$$\text{Rotor torque: } M_{e,AC} = l_e \cdot (p\tau_p)^2 \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta1} \cdot \cos\varphi_i / \pi$$

DC machines:

Current loading A_r and air gap flux density B_δ constant along $\alpha_e \sim 0.7$ of pole pitch τ_p :

$$\text{Rotor torque: } M_{e,DC} = l_e \cdot 2(p\tau_p)^2 \cdot A_r \cdot \alpha_e \hat{B}_{\delta,s} / \pi$$

1. Basic design rules for electrical machines

Specific air gap thrust τ



Specific air gap thrust: Force per surface: $\tau = F / (d_{si} \cdot \pi \cdot l_e)$

Surface: $Area = d_{si} \cdot \pi \cdot l_e = 2p \cdot \tau_p \cdot l_e$

$$F = M_e / (d_{si} / 2) = M_e \cdot \pi / (p \tau_p) \quad \tau = M_e \pi / (2p^2 \tau_p^2 l_e)$$

AC machines:

$$\tau_{AC} = \frac{l_e \cdot (p \tau_p)^2}{\pi} \cdot \hat{A}_{s1} \cdot \hat{B}_{\delta 1} \cdot \cos \varphi_i \cdot \pi / (2p^2 \tau_p^2 l_e)$$

$$\tau_{AC} = \hat{A}_{s1} \cdot \hat{B}_{\delta 1} \cdot \cos \varphi_i / 2$$

DC machines:

$$\tau_{DC} = \frac{l_e \cdot 2(p \tau_p)^2}{\pi} \cdot A_r \cdot \alpha_e \hat{B}_{\delta,s} \cdot \pi / (2p^2 \tau_p^2 l_e)$$

$$\tau_{DC} = A_r \cdot \alpha_e \hat{B}_{\delta,s}$$

1. Basic design rules for electrical machines

Effective current loading



AC machines:

$$\tau_{AC} = \hat{A}_{s1} \cdot \hat{B}_{\delta 1} \cdot \cos \varphi_i / 2$$

$$\tau_{AC} = A_s \cdot k_{w1} \cdot \hat{B}_{\delta 1} \cdot \cos \varphi_i / \sqrt{2}$$

$$A_{s1}(x, t) = \frac{\hat{V}_{s1}\pi}{\tau_p} \cdot \cos(x\pi/\tau_p - \omega t - \varphi_i - \pi)$$

$$\hat{A}_{s1} = \hat{V}_{s1} \cdot \pi / \tau_p = \frac{\sqrt{2}}{\pi} \cdot \frac{m_s}{p} \cdot N_s \cdot k_{ws1} \cdot I_s \cdot \pi / \tau_p = \sqrt{2} \cdot k_{w1} \cdot A_s$$

$$A_s = \frac{2 \cdot m_s \cdot N_s \cdot I_s}{2p \cdot \tau_p}$$


AC: „Fictive“ effective current loading is constant along the air gap circumference!

DC machines:

$$\tau_{DC} = A_r \cdot \alpha_e \hat{B}_{\delta,s}$$

$$A_r(x_s) = A_r = \frac{z \cdot I_c}{d_{si} \cdot \pi} = \frac{z \cdot I_a / (2a)}{2p \cdot \tau_p} = const.$$

DC: Current loading is constant along the air gap circumference!



I_a: Armature current

I_c = I_a/(2a): Coil current

1. Basic design rules for electrical machines

Specific air gap thrust



Electromagnetic torque M_e is determined by air gap flux density B_δ and current loading A (= ampere-turns per unit length) and corresponds with internal power P_δ (air gap power).

- Air gap flux density peak value AC: $\hat{B}_{\delta,1} = 1.0 \text{ T}$, DC: $\hat{B}_{\delta,s} = 1.0 \text{ T}$,
- Typical maximum current loading for air cooling with open ventilation:
 $A = 700 \text{ A/cm}$ (DC-machines), \hat{A}_{s1} corresponding amplitude for AC-machines

a) DC-machines: $\alpha_e = 0.7$: $\tau_{DC} = A_r \cdot \alpha_e \hat{B}_{\delta,s} = 70000 \cdot 0.7 \cdot 1.0 = 49000 \text{ N/m}^2 \cong 0.5 \text{ bar}$

b) AC-machines: $k_{ws1} \approx 0.95$, $\hat{A}_{s1} = \sqrt{2} \cdot k_{w1} \cdot A_s = 940 \text{ A/cm}$,

maximum thrust at $\cos\varphi_i = 1$: $\tau_{AC} = \hat{A}_{s1} \cdot \hat{B}_{\delta,1} \cdot \cos\varphi_i / 2 = 94000 \cdot 1 \cdot 1 / 2 = 47000 \cong 0.5 \text{ bar}$

In reality: $\cos\varphi_i \sim 0.9$, so thrust for AC lower than for DC machines.



Summary:

Torque generation and internal power

- Radial and tangential magnetic forces on magnetized iron and on conductors
- Without any rotor eccentricity the sum of radial forces on stator and rotor sum up to zero
- Tangential forces lead to torque
- Equivalent current loading represents slot conductor arrangement
- Fundamental waves for torque in AC machines
- Internal phase angle φ_i between resulting field wave ($\sim U_h$) and current loading ($\sim I_s$)
- DC machines have bigger torque M_e at the same peak current loading A and field B_δ
- Specific air gap thrust τ as tangent force per area in the range of 0.5 ... 1 bar



1. Basic design rules for rotating machines

1.1 Torque generation and internal power

1.2 Electromagnetic utilization

1.3 Thermal utilization

1.4 Overload capability of AC machines



1. Basic design rules for electrical machines

Air gap torque M_e , air gap power P_δ ,
internal apparent power S_δ



TECHNISCHE
UNIVERSITÄT
DARMSTADT

Air gap torque: M_e

Air gap power (internal power):

AC machines: $P_\delta = M_e \cdot 2\pi n_{syn} = M_e \cdot 2\pi \cdot (f_s / p)$

DC machines: $P_\delta = M_e \cdot 2\pi \cdot n$ n : Rotor speed !

Internal apparent power:

AC machines: $S_\delta = 3 \cdot U_h \cdot I_s$

$U_i (= U_h)$, I_s : Internal stator phase voltage & stator phase current (r.m.s. values!)

DC machines: $P_\delta = U_i \cdot I_a$

U_i , I_a : Induced armature voltage & armature current

DC: $S_\delta = P_\delta$



1. Basic design rules for electrical machines

Internal apparent power S_δ



Internal apparent power S_δ : Induced voltage x current:
$$S_\delta = m_s \cdot U_h \cdot I_s$$

AC machines: Induced phase voltage r.m.s:
$$U_h = \sqrt{2\pi} \cdot f_s \cdot N_s \cdot k_{ws1} \cdot \Phi_h$$

With $\Phi_h = \frac{2}{\pi} \cdot \tau_p l \cdot \hat{B}_{\delta1}$, **r.m.s. current loading** $A_s = \frac{2 \cdot m_s \cdot N_s \cdot I_s}{2p\tau_p}$ and $d_{si} = 2p\tau_p/\pi$

we get:

$$S_\delta = m_s U_h I_s = m_s \sqrt{2\pi} \cdot f_s \cdot N_s \cdot k_{ws1} \cdot \Phi_h \cdot I_s = d_{si}^2 l_e \cdot \frac{f_s}{p} \cdot \frac{\pi^2}{\sqrt{2}} k_{ws1} \hat{B}_{\delta1} A_s$$

DC machines:
$$S_\delta = P_\delta = U_i \cdot I_a$$

Induced armature voltage:
$$U_i = \frac{z \cdot p}{a} \cdot n \cdot \Phi_h$$

With $\Phi_h = \alpha_e \cdot \tau_p l_e \cdot \hat{B}_{\delta,s}$ and **current loading** $A_r = \frac{z \cdot I_a / (2a)}{2p\tau_p}$

we get:

$$S_\delta = P_\delta = d_{si}^2 \cdot l_e \cdot n \cdot \pi^2 \cdot \alpha_e \cdot A_r \cdot \hat{B}_{\delta,s}$$

1. Basic design rules for electrical machines

Electromagnetic utilization C_{δ} per volume & speed



TECHNISCHE
UNIVERSITÄT
DARMSTADT

Rotor volume: $V_r \approx d_{si}^2 \cdot l_{Fe} \cdot \pi / 4 \approx d_{si}^2 \cdot l_e$

Electromagnetic utilization (Esson's number) C :

AC machines:

$$C_{AC} = \frac{S_{\delta}}{d_{si}^2 \cdot l_e \cdot n_{syn}} = \frac{\pi^2}{\sqrt{2}} \cdot k_{ws1} \cdot A_s \cdot \hat{B}_{\delta1}$$

$$C_{AC} = \pi^2 \cdot \tau_{AC} \quad \text{at } \cos \varphi_i = 1$$

DC machines:

$$C_{DC} = \frac{P_{\delta}}{d_{si}^2 \cdot l_e \cdot n} = \pi^2 \cdot \alpha_e \cdot A_r \cdot \hat{B}_{\delta,s}$$

$$C_{DC} = \pi^2 \cdot \tau_{DC}$$

1. Basic design rules for electrical machines

Electromagnetic utilization (*Esson's number*) **C**



The internal apparent power S_δ per stator bore volume $d_{si}^2(\pi/4) \cdot l$ (usually neglecting $\pi/4$) and per speed n_{syn} is called **electromagnetic utilization or *Esson's number C* („figure of merit“)**. It increases with current loading **A** and air gap flux density B_δ .

AC:

$$C_{AC} = \frac{S_\delta}{d_{si}^2 \cdot l_e \cdot n_{syn}} = \frac{\pi^2}{\sqrt{2}} \cdot k_{ws1} \cdot A_s \cdot \hat{B}_{\delta 1}$$

$$A_s = \frac{2 \cdot m_s \cdot N_s \cdot I_s}{2p\tau_p} \quad (\text{r.m.s. current loading})$$

DC:

$$C_{DC} = \frac{P_\delta}{d_{si}^2 \cdot l_e \cdot n} = \pi^2 \cdot \alpha_e \cdot A_r \cdot \hat{B}_{\delta,s}$$

$$A_r = \frac{z \cdot I_a / (2a)}{2p\tau_p}$$

$$M_N \sim S_\delta / n = C \cdot d_{si}^2 \cdot l_e \sim L^3$$

Machine volume (roughly): $V \approx L^3$

Torque determines size of machine, NOT power !

1. Basic design rules for electrical machines

Mounting of air-air heat exchanger on slip ring induction wind generator




TECHNISCHE
UNIVERSITÄT
DARMSTADT

Doubly-fed four-pole
induction wind
generator

$P_N = 1500 \text{ kW}$
 $n_N = 1800/\text{min}$

Axial air inlet fan

- Internal “open” ventilation
- Closed air-circuit to reduce air acoustic noise



Source:
Winergy
Germany

1. Basic design rules for electrical machines

Scaling of power and figure of merit



Example:

AC induction machines: 1500/min
four poles, winding temperature rise 80 K,
air-cooled, open ventilated, for larger rated power

$$C_{AC} = \frac{\pi^2}{\sqrt{2}} \cdot k_{ws1} \cdot A_s \cdot \hat{B}_{\delta1}$$

rated apparent power	S_N	kVA	100	1000	10000
current loading	A_s	A/cm	300	550	1000
air gap flux density	$\hat{B}_{\delta,1}$	T	1.0	1.05	1.1
Esson's number	C	kVA·min/m ³	3.3	6.4	12.2

Result:

At given rotational speed: Bigger power S_N = bigger torque M_N = bigger machine size L = bigger rotor diameter = higher rotor surface speed = better air cooling!

With a better cooling higher current loadings A are possible,
so electromagnetic utilization C increases with rated power S_N .

1. Basic design rules for electrical machines

Figure of merit C



Example: AC induction machine:

Four poles, winding temperature rise 80 K, air-cooled, open ventilated

rated apparent power	S_N	10 000 kVA	}
current loading	A_s	1000 A/cm	
air gap flux density	$\hat{B}_{\delta,1}$	1.1 T	
Esson's number	C	12.2 kVA·min/m ³	

$$C = \frac{\pi^2}{\sqrt{2}} \cdot k_{ws1} \cdot A_s \cdot \hat{B}_{\delta1} \approx \frac{\pi^2}{\sqrt{2}} \cdot 0.95 \cdot 10^5 \cdot 1.1 \approx 732000 \text{ VAs/m}^3 = 12.2 \text{ kVA} \cdot \text{min/m}^3$$

$$C = 732000 \text{ VAs/m}^3 = 732000 \text{ N/m}^2$$

$$C = 732000 \text{ N/m}^2 = \pi^2 \cdot \tau_{AC}$$

$$\tau_{AC} = C / \pi^2 = 74176 \text{ N/m}^2 = 0.74 \text{ bar} \quad \text{at } \cos \varphi_i = 1$$

$$\text{At } \cos \varphi_i = 0.9: \quad \tau_{AC} = 0.74 \cdot 0.9 = 0.67 \text{ bar}$$



Summary: **Electromagnetic utilization**

- Internal apparent power = apparent air gap power S_δ
- Apparent air gap power per rotor volume and speed = electromagnetic utilization
- ESSON's utilization C = „figure of merit“
- Utilization $C \approx 10 \times$ Specific air gap thrust τ
- Utilization C increases with current loading A and air-gap flux density B_δ
- Better cooling = higher current loading A = higher utilization C resp. τ



1. Basic design rules for rotating machines

1.1 Torque generation and internal power

1.2 Electromagnetic utilization

1.3 Thermal utilization

1.4 Overload capability of AC machines



1. Basic design rules for electrical machines


Armature copper losses P_{Cu}



- **AC machines:** m_s phase winding: $P_{Cu} = m_s \cdot R_s I_s^2 = m_s \cdot \frac{N_s \cdot 2(l_{Fe} + l_b)}{\kappa \cdot a_a \cdot A_c} \cdot I_s^2$

$$P_{Cu} = \frac{(l_{Fe} + l_b) \cdot d_{si} \pi}{\kappa} \cdot \frac{I_s / a_a}{A_c} \cdot \frac{2m_s \cdot N_s \cdot I_s}{d_{si} \pi} = \frac{(l_{Fe} + l_b) \cdot d_{si} \pi}{\kappa} \cdot J_s \cdot A_s$$

(c: “conductor”, A_c : conductor cross-section)



Current density per conductor: $J = I_c / A_c$ ($I_c = I_s / a_a$)

- **DC machines:** z armature conductors: $P_{Cu} = R_a \cdot I_a^2 = z \cdot R_c \cdot I_c^2 = z \cdot R_c \cdot \left(\frac{I_a}{2a} \right)^2$

$$P_{Cu} = z \cdot \frac{l_{Fe} + l_b}{\kappa \cdot A_c} I_c^2 = \frac{(l_{Fe} + l_b) \cdot d_{si} \pi}{\kappa} \cdot \frac{I_c}{A_c} \cdot \frac{z \cdot I_c}{d_{si} \pi} = \frac{(l_{Fe} + l_b) \cdot d_{si} \pi}{\kappa} \cdot J \cdot A_r$$

- **General result** for AC and DC machines:

$$P_{Cu} = \frac{(l_{Fe} + l_b) \cdot d_{si} \pi}{\kappa} \cdot J \cdot A$$

1. Basic design rules for electrical machines


Thermal utilization $J_s \cdot A_s$



Heat transfer coefficient α_c , W/(m²K): $P_{Cu} = \alpha_c \cdot A_k \cdot \Delta\vartheta_s$

Steady state temperature rise: $\Delta\vartheta_s = \frac{P_{Cu}}{\alpha_c \cdot d_{si} \pi \cdot (l_{Fe} + l_b)} = \frac{1}{\alpha_c \cdot \kappa} \cdot J_s \cdot A_s$

Stator resistive losses P_{Cu}



$$\Delta\vartheta_s \sim J_s \cdot A_s$$

Result:

- 1) Temperature rise $\Delta\vartheta$ in armature winding for given machine torque M is determined by product of current density J and current loading A .
- 2) It may be reduced by
 - a) superior cooling (increased α_c) or
 - b) decreased losses (increased κ).

1. Basic design rules for electrical machines

Thermal scaling effect $J(L)$



Increasing motor size: Increasing surface of conductors $d_c \pi \cdot l_c$


Example:

Surface $d_c \pi \cdot l_c$ for round conductor wire (wire diameter d_c & length l_c),

Heat transfer coefficient at conductor surface: α_c

Losses per conductor: (conductor volume: $V_c = A_c l_c \sim L^3$)

$$P_{Cu,c} = R_c I_c^2 = \frac{l_c}{\kappa_c A_c} \cdot I_c^2 = \frac{A_c l_c}{\kappa_c} \cdot J^2 \Rightarrow \frac{P_{Cu,c}}{V_c} = \frac{P_{Cu,c}}{A_c \cdot l_c} = \frac{J^2}{\kappa_c} \Rightarrow P_{Cu,c} \sim L^3 \cdot J^2$$



Temperature rise in conductor:

$$\Delta \vartheta = \frac{P_{Cu,c}}{\alpha_c \cdot d_c \pi \cdot l_c} = \frac{(d_c^2 \pi / 4) \cdot l_c}{\kappa_c \cdot \alpha_c \cdot d_c \pi \cdot l_c} \cdot J^2 = \frac{d_c}{4 \cdot \alpha_c \cdot \kappa_c} \cdot J^2 \Rightarrow \Delta \vartheta \sim L \cdot J^2 \quad (d_c \sim L)$$

Result:

Admissible current density J for SAME temperature rise $\Delta \vartheta$ and cooling α_c lower for bigger machines:


$$J \sim 1/\sqrt{L}$$

1. Basic design rules for electrical machines

Totally enclosed doubly-fed induction wind generator



TECHNISCHE
UNIVERSITÄT
DARMSTADT



Fan hood Cooling fins Feet Power terminal box Slip ring terminal box
Shaft mounted fan inside

Surface air-cooled
with iron-cast
cooling fin housing
600 kW at 1155/min

Source:
Winergy
Germany

1. Basic design rules for electrical machines

Example: AC machines thermal utilization



Totally enclosed, surface cooled, for smaller rated power

a) winding temperature rise $\Delta\vartheta = 105 \text{ K}$:

rated power	P_N	kW	5	650
current loading	A_s	A/cm	280	430
current density	J_s	A/mm ²	7.6	5.0
thermal utilization	$A_s \cdot J_s$	A/cm·A/mm ²	2100	2150

b) winding temperature rise $\Delta\vartheta = 80 \text{ K}$:

rated power	P_N	kW	4	570
current loading	A_s	A/cm	240	380
current density	J_s	A/mm ²	6.6	4.4
thermal utilization	$A_s \cdot J_s$	A/cm·A/mm ²	1580	1670

Lower admissible winding temperature $\Delta\vartheta$ rise means lower thermal utilization !



1. Basic design rules for electrical machines

Example: Thermal utilization at Class B and F



Example:

Thermal utilization at Class F (105K) and Class B (80K),
totally enclosed, surface cooled

Rough estimate of power scaling with lower admissible winding temperature:

$$\frac{\Delta \vartheta_B}{\Delta \vartheta_F} = \frac{80}{105} = 0.76 \quad \frac{(A \cdot J)_B}{(A \cdot J)_F} = \frac{1580}{2100} = 0.76$$

$$A \sim I_s, J \sim I_s \Rightarrow \sqrt{A \cdot J} \sim \sqrt{A^2} = A \Rightarrow \frac{A_B}{A_F} = \sqrt{0.76} = 0.87$$

$$\frac{P_{N,B}}{P_{N,F}} = \frac{(B_\delta A)_B}{(B_\delta A)_F} \approx \frac{A_B}{A_F} = \frac{240}{280} = 0.86 \approx 0.8 \quad \longrightarrow$$

$$\boxed{\frac{P_{N,B}}{P_{N,F}} = \frac{4}{5} = 0.8}$$

Lower admissible winding temperature rise $\Delta \vartheta$ means lower rated power P_N !

1. Basic design rules for electrical machines

Example: AC machines thermal utilization



Air-cooled open ventilated, four-pole induction machines,
temperature rise $\Delta\vartheta = 80 \text{ K}$ (at $\vartheta_{\text{amb}} = 40 \text{ }^\circ\text{C}$), rated speed $\approx 1450/\text{min.}$

Rated apparent power S_N / kVA	100	1000	10000
$\hat{B}_{\delta,1} / \text{T}$	1.0	1.0	1.0
$A_s / \text{A/cm}$	300	550	1000
$C / \text{kVA}\cdot\text{min}/\text{m}^3$	3.3	6.1	11.1
machine volume $\sim L^3 / \text{p.u.}$	1.0	5.4	29.7
machine size $L / \text{p.u.}$	1.0	1.75	3.1
$1/\sqrt{L}$	1.0	0.75	0.55
$J_s \sim 1/\sqrt{L} / \text{A/mm}^2$	6.8	5.1	3.7
$A_s \cdot J_s / (\text{A/cm}) \cdot (\text{A/mm}^2)$	2040	2850	3700

Result:

Thermal utilization $A \cdot J$ rises with increased rated power S_N .

Increased current density J for big machines needs improved cooling α_c .

Summary:

Thermal utilization

- $I^2 \cdot R$ losses per cooling surface ~ thermal utilization $A \cdot J$
- Reduced current density J at bigger machine size L for same cooling system
- Thermal scaling laws
- Increased thermal utilization $A \cdot J$ leads to increased ESSON's number $C \sim A \cdot B$
- Thermal Class (B, F, H, ...) of insulation system determines thermal utilization



1. Basic design rules for rotating machines

1.1 Torque generation and internal power

1.2 Electromagnetic utilization

1.3 Thermal utilization

1.4 Overload capability of AC machines



1. Basic design rules for electrical machines

Rated stator impedance x_s of AC machines



$$x_s = \frac{X_s}{Z_N} \quad Z_N = \frac{U_{sN}}{I_{sN}} \quad \text{or} \quad x_d = \frac{X_d}{Z_N} \quad x_s = x_h + x_{s\sigma} \approx x_h$$

$$X_h = 2\pi f \cdot \mu_0 \cdot (N_s k_{ws1})^2 \cdot \frac{2m_s}{\pi^2 p} \cdot \frac{\tau_p l_e}{\delta} \quad (\mu_{Fe} \rightarrow \infty \text{ and no slotting influence})$$

$$x_h = \frac{X_h I_{sN}}{U_{sN}} \approx \frac{X_h I_{sN}}{U_h} = \frac{2\pi f \cdot \mu_0 (N_s k_{ws1})^2 \cdot \frac{2m_s}{\pi^2 p} \frac{\tau_p l_e}{\delta} \cdot I_{sN}}{\sqrt{2} \pi f \cdot N_s k_{ws1} \cdot \frac{2}{\pi} \tau_p l_e \hat{B}_{\delta1}} = \frac{\sqrt{2} \mu_0 k_{ws1}}{\pi} \cdot \frac{\frac{2m_s N_s I_{sN}}{2p \tau_p} \cdot \frac{\tau_p}{\delta}}{\hat{B}_{\delta1}}$$

$$x_h \approx \frac{\sqrt{2} \mu_0 k_{ws1}}{\pi} \cdot \frac{A_s \cdot \frac{\tau_p}{\delta}}{\hat{B}_{\delta1}} \sim \frac{A_s \cdot \frac{\tau_p}{\delta}}{\hat{B}_{\delta1}}$$

$$\frac{1}{x_s}, \frac{1}{x_d} \approx \frac{1}{x_h} \sim \frac{\hat{B}_{\delta1}}{A_s} \cdot \frac{\delta}{\tau_p}$$

1. Basic design rules for electrical machines

Per-unit pull-out power $P_{p0}/S_N, P_b/S_N$



TECHNISCHE
UNIVERSITÄT
DARMSTADT

Synchronous (cylindrical rotor) machines:

$$R_s = 0, X_d = X_q, \vartheta = \pm 90^\circ : \frac{P_{p0}}{S_N} = \pm \frac{3U_p U_{sN} \cdot \sin(90^\circ) / X_d}{3U_{sN} I_{sN}} = \pm \frac{U_p}{U_{sN}} \cdot \frac{U_{sN} / I_{sN}}{X_d} = \pm \frac{u_p}{x_d}$$

Induction machines:


$$R_s = 0, s = \pm s_b : \frac{P_b}{S_N} \approx \frac{P_{\delta b}}{S_N} = \frac{\frac{\omega_{sN}}{p} \cdot M_b}{3U_{sN} I_{sN}} = \pm \frac{\frac{\omega_{sN}}{p} \cdot 3 \frac{p}{\omega_{sN}} \cdot U_{sN}^2 \frac{1-\sigma}{2\sigma X_s}}{3U_{sN} I_{sN}} = \pm \frac{U_{sN}}{I_{sN}} \cdot \frac{1-\sigma}{2\sigma \cdot X_s} = \pm \frac{1-\sigma}{2\sigma \cdot x_s}$$

1. Basic design rules for electrical machines

Overload capability of AC machines




Synchronous machines: Pull out torque



$$\frac{P_{p0}}{S_N} = \frac{u_p}{x_d} \approx \frac{1}{x_d} \sim \frac{\hat{B}_{\delta 1}}{A_s} \cdot \frac{\delta}{\tau_p}$$

Induction machines: Breakdown torque



$$\frac{P_b}{S_N} \approx \frac{1-\sigma}{2\sigma \cdot x_s} \sim \frac{1}{\sigma} \cdot \frac{1}{x_s} \sim \frac{1}{\sigma} \cdot \frac{\hat{B}_{\delta 1}}{A_s} \cdot \frac{\delta}{\tau_p}$$



Summary:

Overload capability of AC machines

- Overload capability = Maximum vs. rated torque M_{max}/M_N
 - DC machine :
Maximum torque simply limited by maximum armature current $I_{a,max} = \text{ca. } 2 \cdot I_N \Rightarrow$
 $\Rightarrow M_{max} = \text{ca. } 1.8 \cdot M_N$ (due to increased iron saturation of armature reaction)
 - Voltage-fed AC machines:
Maximum torque given by
 - a) Induction machine (IM): Breakdown torque M_b
or
 - b) Synchronous machine (SM): Pull-out torque M_{p0}
- Note:
- a) IM: Small stray reactance $X_\sigma \approx \sigma \cdot X_s / 2$
 - b) SM: Small synchronous reactance X_d
lead to increased maximum torque